



*Worldwide repairs carried out with PolymerMetal®*

**REP-# 068**



Because of bad maintenance during the resting period the covers of 3 auxiliary capacitors, each 6 m<sup>2</sup> were affected by erosion of up to 3 cm depth. The volume for filling was obtained by applying 200 kg Ceramium and Hardener CE.

**MultiMetal**  
the MetalExistenceCompany®