




Worldwide repairs carried out with PolymerMetall®

REP-# 044



At the on-load tap changer of a large transformer oil was penetrating through cracks between the top and the on-load tap-changing equipment. The direct-MM-bonding method was used to solve this repair problem. It was carried out with MM-metal oL-steelceramic and Hardener red and afterwards Hardener yellow.

MultiMetall
the MetalExistenceCompany®