



*Worldwide repairs carried out with PolymerMetal®*

**REP-# 122**



Repair of a turbo charger using MM-metal SS-steelceramic. Today MultiMetall recommends the newer product VP 10-500.

**MultiMetall**  
the MetalExistenceCompany®