



*Worldwide repairs carried out with PolymerMetall®*

**REP-# 115**



Repair of a leaking simplex compact packing. The repair was difficult due to oil pouring out of the repair site. Therefore it was decided to use the direct-MM-bonding method by applying the PolymerMetall directly on the greasy surface. Here MM-metal oL-steelceramic with Hardener red was chosen.

**MultiMetall**  
the MetalExistenceCompany®